

ALTRAN Transit Authority

Inspections By Driver

O'Neill, Corey

Right Side- Windows/Lights

Approved

13-Feb-23

Vehicle: 81

Pretrip

84,884

Engine Compartment

Pre-trip Inspection

Fluid Leaks under Bus Approved
 Loose Wires, Hose Connections Approved
 Belts in Engine Compartment Approved
 Oil Level Approved
 Radiator Coolant Level Approved
 Battery Approved

Complete

Approved

Cab Check

Transmission Approved
 Unusal engine noise Approved
 Gauges & Warning Lights Approved
 Switches Approved
 Horn Approved
 Fan & Defrosters Approved
 Wipers & Washers Approved
 Inside & Outside Mirrors Approved
 Brake Pedal & Warning Light Approved
 Operation of Service door Approved
 Driver's Seat Belt/Buckle Approved
 Directional Lights Approved
 Parking or Service Brake Approved
 Steering Approved

Driver Signature

Interior

Emergency Equipment Approved
 First Aid/Bio Hazard Kit Approved
 Entrance Steps Approved
 Cleanliness of Interior Approved
 Condition of Floor Approved
 Emergency Door & Buzzer Approved

Exterior

Headlights, Flashers/4 Ways Approved
 Right Front Tire & Wheel Approved
 Front of Bus-Windshield Approved
 Left Front Tire & Wheel Approved
 Exhaust System Approved
 Left Side- Windows/Lights Approved
 Left Rear Tires & Wheels Approved
 Rear of Bus-Windows/Lights Approved
 Tail Pipe Approved
 Right Rear Tires & Wheels Approved